 FOR OFFICIAL USE				
National Qualification 2019	S		Mark	(

X861/75/01

Practical Metalworking

MONDAY, 29 APRIL 2:30 PM - 3:30 PM



Full name of cer	ntre			Town	
Forename(s)		Sur	name		Number of sea
Date of birt	:h Month	 Year		candidate ı	

Total marks — 60

Attempt ALL questions.

Write your answers clearly in the spaces provided in this booklet. Additional space for answers is provided at the end of this booklet. If you use this space you must clearly identify the question number you are attempting.

Use blue or black ink.

Before leaving the examination room you must give this booklet to the Invigilator; if you do not, you may lose all the marks for this paper.





Total marks — 60 Attempt ALL questions

1. A brass door plate for a sports changing room is shown below.




Brass is an alloy.


(a)	State what the term 'alloy' means.	1
-----	------------------------------------	---

(b) State one property of brass.


The image below shows an attempt at marking out multiple door plates on a sheet of brass.



(c) Explain why the image above demonstrates poor practice in marking out.You may use sketches to support your answer.




Fixing screws are to sit flush with the face of the door plate as shown.



(d) Describe how to use a pedestal/pillar drill to create the holes for the fixing screws.

3

You may use sketches to support your answer.



* X 8 6 1 7 5 0 1 0 4 *

[Turn over for next question

DO NOT WRITE ON THIS PAGE

page 05


A metal skipping rope handle made of two separate parts is shown below.





The working drawing for manufacturing the baton is shown below.

Baton





2

From the information given in the working drawing

- (i) explain what is meant by the term 'M5 \times 12' (a)

 - (ii) state the outside diameter of the baton. 1


_____ mm

page 06

2

2. (continued)

The elevation of the baton is shown below.



Elevation


(b)	State the name of the turning process used to create feature A, shown above.					
(c)	Describe two personal health and safety procedures which must be followed when carrying out a turning process. 1					
	2					



page 07

2. (continued)

Two pupils have set up the centre lathe for knurling as shown below.



pupil A pupil B

(d) (i) Explain why pupil A is more likely to have a better knurled finish on their workpiece.

(ii) Name the part of the centre lathe that holds the knurling tool.


(e) State **two** properties of aluminium that make it a suitable material for the baton.

1_____

2_____


2. (continued)

Enlarged views of the blind hole on the baton are shown below.




- (f) Explain why a centre lathe, rather than a pedestal/pillar drill, was used to drill the blind hole.
- (g) Explain why a 'plug tap' is used when creating an internal thread on a blind hole.

An enlarged view of the chamfer on the baton is shown below.



(h) Describe how the chamfering process is carried out on the centre lathe.2You may use sketches to support your answer.

A lathe tool used in the manufacture of the baton is shown below.



(i) Explain the purpose of this tool.

1


The hook is shown below.



The hook must be annealed before bending to shape.

_	

The tools shown below were used to cut the external thread on the hook.




(k) Name each of the tools shown.




3. A centre finder is shown below.

It is made up of two parts with a nut and bolt joining them together.




The locator is made from 3 mm thick mild steel and is marked out as shown below.



- (a) Explain why the metal was centre punched before drilling the hole.
- (b) Name the hand tool that would be used to remove the majority of the waste material.

1

The tool shown below was used in the manufacture of the centre finder.



(c)	(i)	Name this tool.	

1

(ii) Describe the purpose of this tool.

1

When drilling metal, twist drills should be set at an appropriate speed.

(d) Identify which twist drill should be set at a higher speed when drilling metal, by ticking (✓) a box below.

1



12 mm twist drill



3 mm twist drill



When drilling, swarf is created.



(e)		e one safety precaution that should be taken when clearing swarf drilling.	1
(f)	•	nted finish is applied to the centre finder. Explain one reason why this is a suitable finish.	1
	(ii)	Describe one method of applying paint to the centre finder.	1





page 15

3. (continued)


Two dimensions from the shaft are shown on the drawing below.

Dimensional tolerances from the title block are also shown.





(g) (i) Identify the reading which is within tolerance when checking the $\emptyset 10$ mm dimension, by ticking (\checkmark) a box below.







page 16

3. (g) (continued)


hhhhhh

(ii) Identify the reading which is within tolerance when checking the 60 mm dimension, by ticking (\checkmark) a box below.






60.48



page 17

4. A metal shovel, made from two parts, is shown below.




- (a) All parts of the shovel are manufactured from the same metal.
 - (i) Explain why this is an advantage when recycling.

1

(ii) State one reason why recycling metal is important.

1

The blade has to be marked out as shown on the drawing below.




(b) Describe how to accurately mark the R15, on the corners of the blade.You must make reference to all tools, processes and relevant dimensions.You may use sketches to support your answer.



(continued)

It is good practice to use a centre punch to lightly mark lines after scribing, as shown below.




- (c) State the name of this process.
- (d) State two safety checks that should be carried out on a pedestal/pillar drill prior to switching on. 2

MARKS DO NOT WRITE IN THIS MARGIN

4. (continued)


After drilling, one of the holes ended up with a ragged edge on the underside of the material as shown below.



(e)	Describe how to remove the ragged edge.	1

page 21

The corners of the shovel blade are to be joined by brazing as shown below.



(f) Describe the process of brazing the corners.You may use sketches to support your answer.




ARKS	DO NOT
	WKITETIN
	THIS
	MARGIN

4. ((cor	tin	ued)
4.	LUI	ILIII	ucu

The shovel is to be finished by bluing.

(g) Describe the process of bluing.

(h) The handle and the blade are joined together by the process of riveting as shown below.



(i) Name the type of rivet shown.

1

(ii) Complete the procedure for describing how the blade is riveted to the handle.

2

1 Cut the rivet to the correct length.

۷ _

3 Swell the rivet with the flat face of the hammer.

4 Form the rivet head with the ball pein of the hammer.

5

(i) Complete the table below by either describing the purpose of the tool or stating the name of the tool.

Tools	Purpose of tool	Name of tool
		Folding bars
		Tin snips
	To strike metal or other tools or to shape metal.	
		Hide mallet
	To join two pieces of sheet metal together through pre drilled holes.	

[END OF QUESTION PAPER]



page 25

MARKS DO NOT WRITE IN THIS MARGIN

ADDITIONAL SPACE FOR ANSWERS



page 26

MARKS DO NOT WRITE IN THIS MARGIN

ADDITIONAL SPACE FOR ANSWERS



page 27

[BLANK PAGE]

DO NOT WRITE ON THIS PAGE

Acknowledgement of copyright

Question 2 antoniodiaz/shutterstock.com Question 3 (e) Lukas Gojda/shutterstock.com



page 28