

COSVR708 - SQA Unit Code F3DN 04

Maintain the dimensional accuracy of the work



Overview

This standard is about

- 1 providing sufficient clear and accurate dimensional information
- 2 observing and checking dimensional controls
- 3 correcting dimensional deviations and making allowances for different circumstances

COSVR708 - SQA Unit Code F3DN 04

Maintain the dimensional accuracy of the work

Performance criteria

- You must be able to:*
- P1 ensure the workforce is provided with sufficient clear and accurate information to enable them to position, align and/or level the work
 - P2 observe and check dimensional controls and record the results to meet quality standards
 - P3 identify any deviations in position, alignment or level and take measures to correct them promptly
 - P4 recommend revised work procedures and practices to minimise deviations and to allow for different circumstances and conditions

COSVR708 - SQA Unit Code F3DN 04

Maintain the dimensional accuracy of the work

Knowledge and understanding

You need to know and understand:

Performance Criteria 1

Provide dimensional information

- K1 how to provide, clear and accurate information on **dimensional controls**
- K2 how to ensure the dimensional information is sufficient

Performance Criteria 2

Observe and check dimensional information

You need to know and understand:

- K3 how to observe and check **dimensional controls**
- K4 how to record observed results
- K5 how to compare observed results against given quality standards

Performance Criteria 3

Identify deviations

You need to know and understand:

- K6 how to identify **deviations** in **dimensional controls**
- K7 how to correct **deviations**

Performance Criteria 4

Recommend revised work procedures and practices

You need to know and understand:

- K8 how to revise work procedures for **dimensional controls**
- K9 how to recommend revised procedures for different **circumstances and conditions**
- K10 why you need to revise work procedures to minimise **deviations** in dimensional control

COSVR708 - SQA Unit Code F3DN 04

Maintain the dimensional accuracy of the work

Additional Information

Scope/range related to performance criteria

Performance Criteria 1

- 1 records of dimensional information for at least four of the following
 - 1.1 lines
 - 1.2 levels
 - 1.3 angles
 - 1.4 distances
 - 1.5 curves
 - 1.6 position
 - 1.7 setting out points
 - 1.8 loads
 - 1.9 centres of gravity

Performance Criteria 2

- 2 records of checks conducted compared to the quality standards provided for the project

Performance Criteria 3

- 3 records of deviation arising from at least one of the following and the actions taken to correct them
 - 3.1 transfer of lines and levels
 - 3.2 use of incorrect lines and levels
 - 3.3 calculations
 - 3.4 given information

Performance Criteria 4

- 4 records of recommendation made considering at least one of the following circumstances and conditions
 - 4.1 environment
 - 4.2 unforeseen
 - 4.3 planned

COSVR708 - SQA Unit Code F3DN 04

Maintain the dimensional accuracy of the work

Scope/range related to knowledge and understanding

Circumstances and conditions

- 1 environmental
- 2 unforeseen
- 3 planned

Deviations (arising from)

- 4 transfer of lines and levels
- 5 use of incorrect lines and levels
- 6 calculations
- 7 given information

Dimensional controls

- 8 lines
- 9 levels
- 10 angles
- 11 distances
- 12 curves
- 13 position
- 14 setting out points
- 15 loads
- 16 centres of gravity

COSVR708 - SQA Unit Code F3DN 04

Maintain the dimensional accuracy of the work

Developed by ConstructionSkills

Version number 2

Date approved March 2008

Indicative review date July 2015

Validity Current

Status Original

Originating organisation ConstructionSkills

Original URN VR708

Relevant occupations Construction and Building Trades Supervisors

Suite Construction Site Supervision; Controlling Lifting Operations (Construction)

Key words Dimensional; Accurate; Observing; Checking; Allowances