

Areas of potential duplication in 'Practical Training Activities'.

CARPENTRY & JOINERY.

Training Activity	PDA/TAPs
Manufactured Door. Practice mid/bottom rail joint.	Door Construction.
Fit Window.	First Fix. Second Fix.
Make pipe box as a metal partition, this will involve crimping and fixing	Timber Frame Construction & Internal Partitioning Systems.
Fascia soffit on only one of Truss Roof or Pitched Roof.	Roof Construction.
Risk Assessment for each TAP only.	All PDA/ TAPs